

FIG. 1 is a schematic diagram of a mechanical assembly, showing a cross-sectional view of a device with various components labeled with reference numerals.




FIG. 1




FIG. 2








FIG. 3

350T33.tif 66




FIG. 4

5




FIG. 5








FIG. 8









FIG. 9











FIG. II




FIG. 12




FIG. 13




FIG. 14




FIG. 15





FIG. 16

(a)



(b)




FIG. 17



2007-07-07 14:26:00




FIG. 19




FIG. 20





FIG. 21

